

Socket Cap Size Chart

www.boltdepot.com/tools



#2-56



#4-40



#6-32




#8-32




#10-24



#10-32




#12-24




1/4"-20




1/4"-28




5/16"-18



5/16"-24




3/8"-16




3/8"-24




← Length →




7/16"-14




7/16"-20




1/2"-13



1/2"-20



9/16"-12



9/16"-18

Fastener length is measured from where the material surface is assumed to be, to the end of the fastener.



Scale Check: After printing, measure ruler above to ensure correct scale